

BASE Buildings Physical Characteristics: Buildings with Operable Windows

Buildings with Operable Windows	Number of Buildings Reporting ¹
Yes	44
No	55
Total Number of Buildings Reporting	99

Notes:

¹This table was compiled by assigning “yes” to any building that indicated an operable window percentage of greater than 0. Specifically, 44 buildings indicated a percentage of operable windows greater than 0; while 55 buildings indicated 0% operable windows. Ninety nine buildings reported a response for operable window percentages. One building was not equipped with windows.

Variable Description:

Buildings with Operable Windows describes the number of BASE buildings that had operable windows.