

**SITE PHOTOGRAPHS**  
**REMEDIAL ACTION FOR OPERABLE UNIT 2**  
**RESIDENTIAL SURFACE SOILS**  
**TAR CREEK SUPERFUND SITE, OTTAWA COUNTY, OKLAHOMA**



**Excavation of Contaminated Soils From A Residential Area**



**Remediated Property - Note the chat pile in the background and the recently placed sod and limestone driveway in the foreground.**

**SITE PHOTOGRAPHS**  
**REMEDIAL ACTION FOR OPERABLE UNIT 2**  
**RESIDENTIAL SURFACE SOILS**  
**TAR CREEK SUPERFUND SITE, OTTAWA COUNTY, OKLAHOMA**



**Picher Sports Complex - The complex is constructed on a former mine waste site.**



**Remediated Playground - The playground is located in Picher.**